वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VF-10A	Not healthy. found Overload trip	Reset done	00:20:00	00:30:00	
2	OHP	WOBR ON CO-6A	All drives not working. ACB tripped	Made ON	05:25:00 22:30:00	05:35:00 22:40:00	
3	OHP	WOBR ON CO-29	LT complaint. checked and found OK	.	01:45:00	01:55:00	
4	OHP	TBS ON CO-20	LT complaint. M-4 tripped	Reset done	02:35:00	02:50:00	
5	OHP	BRC ON CO-31	Yard running indication not coming. Probe damaged	Probe replaced and tested OK	04:00:00	04:20:00	
6	OHP	BRS OF CO-5A	Mechanical BRS circuit is OK. But orientation is not correct. Will not work properly. Electronic BRS sensors and module not compatible due to circuit problem.	Installed 24v siemens relay temporarily and made OK.	22:30:00	00:10:00	No electrical delay. Mechanical BRS to be installed properly. Sensor confi guration to be changed and relay can be removed
7	CHP	CC-131	Overload acted	Reset done	23:40:00	01:15:00	4 times
8	CHP	CC-54	Overload acted	Reset done	00:00:00 23:30:00	00:05:00 23:40:00	

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
9	CHP	SCR-2 ON CC-33	TUL chute sensor acted. Found acting due to water	Bypassed	05:00:00	05:15:00	Bypass to be removed
10	WT	OP-2	Breaker tripped in LC. Spark observed on neutral bus bar. suspected insulator puncture. checked the trolley line and found healthy.	Motor-5 cable R-phase getting touched with pusher. Proper lugging and re termination done	00:30:00	01:20:00	
11	IOSA	FLS WOBR	Bucket wheel not running. Found bucket wheel struck up.	Made reverse and made free.	02:10:00	02:25:00	No electrical delay