वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 05/11/2026

Shift: B

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VF-10A	Drive not healthy. found M-1 MPCB tripped	Reset done	15:30:00	15:50:00	
2	OHP	WOBR ON CO-25	Luffing not working. Found UP limit switch stuck up	Released and made OK	15:45:00	16:00:00	
3	OHP	CO-26	Reported RED. OLR acted	Reset done	16:50:00 18:55:00	16:55:00 19:05:00	
4	OHP	VS-2A	Reported RED. OLR acted	Reset done	19:50:00 20:25:00	20:00:00 20:35:00	
5	OHP	BRC ON CO-33M	B/W stopping on ZSS. Sensor supply to be checked.	Bypassed in module. CT found not moving. CT guide roller problem	19:55:00	20:10:00	Informed to mechanical
6	OHP	CO-25	Overload acted	Reset done	20:45:00 21:15:00	20:55:00 21:25:00	
7	CHP	CC-51	MPR tripped to stop feeding conveyor	reset done	16:45:00	16:50:00	
8	CHP	CC-51A	Tripped on Overload	Reset done	18:55:00 19:55:00	19:00:00 20:00:00	
9	CHP	CC-215	Tripped on overload	Reset done	15:18:00 17:35:00	15:28:00 17:45:00	
10	CHP	STK-3 ON CC-112	Slew not working. Found material jamming at slew area	Informed to operation	15:50:00	16:05:00	No electrical delay
11	CHP	RECL-1 ON CC-36	B/C not running. Found chute sensor core earth fault and ZSS return core earth fault.	Chute sensor kept bypass in I/O rack.	16:45:00	17:30:00	To be rectified
12	CHP	CC-107	Overload acted	Reset done	17:15:00	17:25:00	