वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: C

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | VF-10A | Not healthy. found Overload trip | Reset done | 00:20:00 | 00:30:00 | |
| 2 | OHP | WOBR ON CO-6A | All drives not working. ACB tripped | Made ON | 05:25:00<br>22:30:00 | 05:35:00<br>22:40:00 | |
| 3 | OHP | WOBR ON CO-29 | LT complaint. checked and found OK | . | 01:45:00 | 01:55:00 | |
| 4 | OHP | TBS ON CO-20 | LT complaint. M-4 tripped | Reset done | 02:35:00 | 02:50:00 | |
| 5 | OHP | BRC ON CO-31 | Yard running indication not coming. Probe damaged | Probe replaced and tested OK | 04:00:00 | 04:20:00 | |
| 6 | OHP | BRS OF CO-5A | Mechanical BRS circuit is OK. But orientation is not correct. Will not work properly. Electronic BRS sensors and module not compatible due to circuit problem. | Installed 24v siemens relay temporarily and made OK. | 22:30:00 | 00:10:00 | No electrical delay. Mechanical BRS to be installed properly. Sensor confi guration to be changed and relay can be removed |
| 7 | CHP | CC-131 | Overload acted | Reset done | 23:40:00 | 01:15:00 | 4 times |
| 8 | CHP | CC-54 | Overload acted | Reset done | 00:00:00<br>23:30:00 | 00:05:00<br>23:40:00 | |

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: C

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 9 | CHP | SCR-2 ON CC-33 | TUL chute sensor acted. Found acting due to water | Bypassed | 05:00:00 | 05:15:00 | Bypass to be removed |
| 10 | WT | OP-2 | Breaker tripped in LC. Spark observed on neutral bus bar. suspected insulator puncture. checked the trolley line and found healthy. | Motor-5 cable R-phase getting touched with pusher. Proper lugging and re termination done | 00:30:00 | 01:20:00 | |
| 11 | IOSA | FLS WOBR | Bucket wheel not running. Found bucket wheel struck up. | Made reverse and made free. | 02:10:00 | 02:25:00 | No electrical delay |