



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

#### ELECTRICAL SHIFT REPORT

Date: 17/06/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

| Sl No | Area | Equipment       | Problem                           | Action                                                                                         | From     | To       | Remarks |
|-------|------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | wobr-2 on co-29 | luff not taking place             | olr acted, reset done                                                                          | 09:25:00 | 09:40:00 |         |
| 2     | OHP  | brc-5 on co-32  | no drives operating               | acb tripped, made on and tested all drives                                                     | 09:20:00 | 09:30:00 |         |
| 3     | OHP  | TT-1 on co-7a   | position indication is not coming | cable issue to be checked., bypassed at io rack and given for clearance for operation.         | 11:35:00 | 12:00:00 |         |
| 4     | OHP  | tbs-6 on co-7a  | no drives starting                | acb tripped, made on                                                                           | 11:35:00 | 11:55:00 |         |
| 5     | OHP  | tbs-6 on co-7a  | LT not stopping with load         | Brakes are not working , regulation along with mechanical is done.                             | 12:10:00 | 12:30:00 |         |
| 6     | OHP  | tbs-3 on co-21  | reported stopped on cjd 3 times   | kept bypass temporarily, checked along with instrumentation, and restored in circuit later on. | 10:00:00 | 10:20:00 |         |
| 7     | OHP  | TIS-2           | TIS-2 mpcb tripped                | reset done, kept bypass at io rack due to lump tripping as per operation requirement.          | 08:00:00 | 08:10:00 |         |
| 8     | CHP  | S-3 on cc-111   | BC not operating ,                | slew is at 30 degrees, asked operator to operate slew OHP side, and started BC.                | 07:40:00 | 07:55:00 |         |
| 9     | CHP  | s-3 on cc-111   | yard conveyor stopped             | due to comm. issue yard stopped, LT done and communication was restored.                       | 08:20:00 | 08:35:00 |         |
| 10    | CHP  | scr-5 on cc-38  | TUL CJD acted,                    | material cleaned, and checked CJD operation and gave clearance for operation.                  | 08:00:00 | 08:10:00 |         |
| 11    | CHP  | cc-54           | tripped on OLR 5 times            | tripped due to deck sheets jamming, cleaned and reset done                                     | 09:00:00 | 10:15:00 |         |
| 12    | CHP  | cc-51           | feeding conveyor tripped 3 times  | due to overload                                                                                | 11:00:00 | 13:15:00 |         |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 17/06/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: A

| Sl No | Area | Equipment           | Problem                     | Action      | From     | To       | Remarks |
|-------|------|---------------------|-----------------------------|-------------|----------|----------|---------|
| 13    | CHP  | cc-201,203, 204,205 | not healthy                 | reset done. | 07:30:00 | 07:40:00 |         |
| 14    | WT   | ot-3 D2             | TRIPPED ON 43 ENCODER FAULT | reset done  | 13:15:00 | 13:20:00 |         |
| 15    | WT   | ot-3 d1             | tripped on encoder 43 fault | reset done  | 13:00:00 | 13:10:00 |         |
| 16    | WT   | co-4 carriage drive | tripped due to jamming      | reset done  | 13:35:00 | 13:45:00 |         |