वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 29/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on co 19	Left BC not working,OLr acted	reset	14:50:00	15:15:00	
2	OHP	BRC on CO 32	LT not working ,D2 olr acted	OLR reset	16:30:00	16:40:00	
3	OHP	CR 3	mpr tripped due to Oc	reset	16:40:00	16:50:00	
4	OHP	TBs on CO 21	right luff not working	checked found no power supply to motor due to malfunctioning of OLR and bridge rectifier of brake ckt fully rusted and one side connector broken	20:00:00	22:00:00	told agency to bring spare for OLR and bridge rectifier and to be changed(pending)
5	OHP	CBMS on CO6A	mpcb tripped immediately after cmd	water inside motor,IR value zero	18:50:00	22:00:00	motor changing going on
6	CHP	LC 17 and 18	no power,in LBDS FDR1 tripped in DMT	reset it and normalize LC17 and 18 both i/c 1 and 2 made on b/c made off	14:45:00	15:15:00	
7	IOSA	BRC	Lt not working,s/s in local	kept in remote	14:20:00	14:30:00	