



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/08/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT4	Reported not moving	Control supply fuse blown.Replaced and tested okay	19:00:00	19:15:00	
2	OHP	Cc-110	ZSS acted	Probe gap more.Adjusted and tested okay	18:35:00	19:00:00	
3	OHP	CO-34A	PC acted	Wrong complaint	15:05:00	15:10:00	
4	OHP	TBS on CO-22	LT not taking place	Drive tripped.Reset done(2 times)	15:50:00	16:35:00	
5	OHP	WOBR on CO-29	B/W not running	MCCB tripped.Motor winding cable got pressed by TB due to heavy vibration.Cable insulation damaged.Cable straight feroule put and terminated directly.Tested okay	17:15:00	19:30:00	Motor TB cover to be provided
6	OHP	BRC on CO-32	B/W-2 not running	Checked and found no electrical problem.B/W got struck.	18:50:00	19:25:00	Informed to operation
7	OHP	CO-25	Reported tripped	OLR acted.Reset done	18:50:00	19:00:00	
8	OHP	BRC on CO-8A	B/W-2 not running	Reverse solenoid pressed.Made free and tested okay.NO electrical problem	20:55:00	21:25:00	
9	OHP	TBS on CO-20	Lt not taking place	PCRD tension acted due to guide problem	21:00:00	21:25:00	Informed to mechanical
10	OHP	BRC on CO-8A	CT not taking place	Wrong complaint.B/W's found embedded in material	19:50:00	20:10:00	
11	OHP	WOBR on CO-25	Lt not taking place	Due to track jamming	21:40:00	21:50:00	Informed to operation
12	CHP	CC-33 SCR-2	LT not taking place	PCRD drum sensor acted.Reset done and tested okay	17:50:00	18:05:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/08/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	IOSA	OC-21A	Reported failed to start	PC hardware contact bypassed and tested okay	18:00:00	18:30:00	PC hardware contact is in bypass.To be rectified