



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/07/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	vs-1 motor	NDE side bearing sound observed,	motor changed with spare one and trail run is rakrn.	14:45:00	16:45:00	
2	OHP	tbs-5 on co-24	reported no power, coupler flasover took place due to moisture, and fixed coupler head got damaged,	DNW is informed , head replaced, CLeaning was done, Megger done towards both ends, found ok.	19:15:00	22:30:00	
3	CHP	SCR-2 ON CC-33	LT not working. Drive tripped	Reset done	17:50:00 19:30:00	18:00:00 19:40:00	
4	CHP	CC-215	Motor Overload trip	Reset done	21:45:00	21:55:00	
5	CHP	CC-115	BRS not getting reset. Alignment found disturbed	Proper alignment done and made OK	21:30:00	21:50:00	
6	WT	ot-3	d1 tripped due to encoder fault 43	reset done	19:35:00	19:40:00	
7	IOSA	l and t Wobr	reported hydraulic pump stopping	low oil level was acting, informed mechanical.	18:45:00	19:00:00	