



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 02/08/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	SCR-10 on CC-105	B/C not running in Reclaiming mode	Yard running signal missing.Bypass removed from program and tested okay	07:15:00	07:30:00	
2	OHP	CMBS-4A on CO-2A	Reported not running	MPCB made on and tested okay	09:30:00	09:40:00	
3	OHP	CO-26	Reported tripped	OLR acted.Reset done	13:40:00	13:50:00	
4	OHP	WOBR on CO-29	Reported B/W not running	Checked and found MCCB tripped.Winding lug got cut at motor TB.Motor meggered and found motor burnt.Spare motor found and replaced.Alignment is going on.	10:45:00	14:30:00	
5	CHP	SCR-9 on CC-104	PLC not communicating	Ethernet cable checking done.Ethernet switch port problem found.Ethernet Cable from PLC to modem connected directly to PLC port and tested okay	06:00:00	07:30:00	
6	CHP	CC-39 SCR-5	TUL CS problem	Rectified and tested okay	09:30:00	09:45:00	
7	CHP	CC-27	Reported tripped	OLR acted.Reset done	06:40:00	06:50:00	
8	CHP	Cc-131	MPD tripped	Reset done	12:10:00	12:15:00	
9	CHP	CC-52	MPD tripped	Reset done	12:10:00	12:15:00	
10	CHP	Cc-51	MPD tripped	Reset done.	09:50:00 12:05:00	09:55:00 12:10:00	
11	WT	OP-9	Reported not moving forward	LS-5 bypassed and tested okay	09:40:00	09:50:00	Rectified after rake completion