



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-14	MCCB was tripping on start	LM400, MCCB failed, replaced with spare module, motor meggered, tb checked found ok and trail run taken.	06:40:00	07:30:00	Found balanced currents, 102A.
2	OHP	CR-2	tripped on oil flow fault	reset done	10:10:00	10:15:00	no electrical problem
3	OHP	WOBR-4 on co-6a	hydraulic pump stopping on slew command , due to CP-2 fault	observed charge pressure dropping, informed Operation.	11:30:00	11:45:00	no electrical problem
4	OHP	co-50	dmpr tripped on olr	reset done	10:00:00	10:15:00	
5	CHP	CC 14	Ol原因 Acted Due to Jamming in Tail end	Reset and Informed to oprn	12:20:00	12:30:00	
6	CHP	CC 52	Feeding conv OLR acted	Reset	11:15:00	12:15:00	2 times
7	IOSA	TBS	Found RBC zss probe not working	probe replaced and tested	10:20:00	10:20:00	no delay