RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

वी.एस.पी
VSP

Date: 12/11/2026

Area: OHP

Equipment	Job
brc-4 on co-8a	D1 chp side, M1 motor checked and connected back in circuit, found brake 1 mpcb aux. contact loose, fixed back properly,
tbs-7 on co-19	pcrd pendulum switch contact issue rectified and checked pcrd operatins, cable winding done onto drum.
Repair Bay WOBR-2	1) LT brake panel is shifted outside MCC , Aux. MCC Interlock panel is also removed to make space for RIO installation. 2) Slip ring PPM is done, LT motors checked, cleaned and covered with plastic covers. 3)Luff, Slew limits checked and covered with plastic.
Misc.	1) OM-24 control bus PPM is done. 2) BPC-1 safety devices ppm is done. 3) co-8,9,10 gallery illumination is improved. 4) Ground hoppers VF unbalance motors set inspection is done and recorded. 5) wobr-3 on co-25 BW motor and BC motor inspection is done.
vf-1a,2a,bf-3a,4a,5a; co-17; co-60,63,BPC-1	motor and panel side ppm is done.
1-141LC4 IC-1	Found 11KV not available , Protection relay at 1-14LBDS1 feeder failed, replaced with spare feeder's relay ,and charged 11KV, LT side should be charged only during emergency until protection relay is configured.
1-14LC7 IC-2	Transformer 2 Bucholz relay acted, Oil top up done by DNW, Incomer2 made on and bus coupler made off.