



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 31/07/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-5A	ZSS acting	Checked and found probe return wire problem.Rectified but still zss acting in between	10:50:00	11:20:00	To be checked furthur
2	OHP	TBS on CO-22	LT not taking place	Checked and found M-3 acted.Reset done	12:00:00	12:10:00	
3	CHP	CC-109 SCR-9	Operator cabin adjustment not working	Two fuses blown in I/O rack.Replaced and tested okay	06:30:00	07:00:00	
4	CHP	TT on CO-103 on CC-104	Position bit missing	Bit bypassed at I/O rack.	06:45:00	06:55:00	
5	CHP	CC-26A TT	TT not moving	MPCB tripped.Made on	12:20:00	12:30:00	
6	CHP	CC-52	MPD tripped	Reset done	07:20:00 10:15:00 13:30:00	07:30:00 10:25:00 13:40:00	
7	CHP	CC-58	Reported faulty	Checked and found TT chute sensor no power.MPCB tripped.Made on and tested okay	07:20:00	07:45:00	