



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/08/2026

Incharge(s): Lal Singh

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT-3	LT NOT WORKING ..GLASS FUSE BLOWN DUE TO CABLE INSULATION DAMAGE NEAR PUSH BUTTON	CABLE INSULATION PROVIDED AND FUSE REPLACED	00:00:00	00:25:00	
2	OHP	CO-25	TRIPPED ON OLR	RESET DONE	00:10:00 04:25:00	00:20:00 04:35:00	
3	CHP	CC-112 SCR-8	BC TRIPPED ON OLR	RESET DONE	23:55:00	00:15:00	
4	CHP	CC-33 SCR-2	BC ZSS PROB PROBLEM	PROB REPLACED AND TESTED	01:25:00	01:50:00	
5	CHP	CC-58	TRIPPED ON SP FAULT	RESET AND TESTED .. CURRENTS FOUND BALANCED	02:40:00	03:00:00	
6	WT	OT-3	D1 TRIPPED ON 43ENCODER FAULT	RESET DONE	01:25:00	01:30:00	
7	IOSA	OC-14A	STOPPED WITHOUT FAULT	PULL CORD HARDWARE CONTACT BYPASSED	01:20:00	01:45:00	