



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/07/2026

Shift: B

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	LC-8,LC-7,L C-6,LC-5,L C-4,LC-3,1- 141LC4	I/C-2 LT side ACB's	BUSCOUPLERS made OFF AND I/C-2 made ON.	14:30:00	15:30:00	OHP,CHP,I OSA all LC incomers normalized.
2	OHP	co-35	RI defect at panel O/G R phase observed	R phase termination tightened, to be checked further.	16:30:00	16:45:00	
3	OHP	co-29 cjd	reported not getting reset	Sensitivity was adjusted and its operation checked.	19:00:00	19:20:00	
4	OHP	TIS-3	reported failed to start	estop acted.	19:00:00	19:20:00	Temporarily bypassed, estop released and restored in circuit.
5	OHP	BRC-2 on CO-30	NO POWER. Two HT fuses blown	checking is under progress	21:15:00	22:00:00	
6	CHP	CC-201	OLR acted	reset done	15:00:00	15:10:00	
7	CHP	CC-201	pullcord acted	Reset done	15:10:00	15:20:00	
8	CHP	CC-13	OLR acted	Reset done	17:00:00	17:10:00	
9	CHP	CC-131	OLR acted	Reset done	17:00:00	17:05:00	
10	CHP	CC-52	MPR acted	Reset done	21:30:00	21:35:00	
11	CHP	CC-215	OLR ACTED	Reset done	21:10:00	21:20:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/07/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	SCR-8 ON CC-111	HT Cable got crushed under LT wheel and punctured. LC-2 incomer-2 tripped.	LC-2 incomer-2 made ON and SCR-10,CC-126 power restored. Cable joint by DNW is under progress	20:40:00	22:00:00	
13	WT	CP-3	reported stopped while moving back after rake	found plc was not in run mode.knob on cpu changed to stop and back to run mode.	20:30:00	20:55:00	