वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 28/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-7A	LT not working. Drive tripped	Reset done	22:30:00	22:40:00	
2	OHP	RSCO-6A	Carriage drive tripped	reset done	22:45:00	22:55:00	
3	OHP	WOBR ON CO-25	Slew not working. Drive tripped	Reset done	23:10:00	23:25:00	
4	OHP	TBS ON CO-7A	Reported LT going forward without command. Also found Local/Remote selector switch side one wire found open. Reconnected	Mechanical brake adjustment done	23:50:00	00:10:00	
5	OHP	CO-34	Reported RED. Found OLR acted	Reset done	00:50:00	00:55:00	
6	OHP	BRC ON CO-28	LT not working. Found Drive tripped on Earth fault.	M-2 cable disconnected and drive reset done	01:25:00	01:50:00	motor to be checked
7	OHP	TBS ON CO-21	Right boom luffing not working due to brake jamming	Brake made free and OK	01:45:00	02:10:00	
8	OHP	CO-11 TO CO-16	Reported shuttle conveyor position not coming.	checked and found OK	02:10:00	02:20:00	
9	OHP	WOBR ON CO-6A	LT not working. Drive tripped.	M-1 disconnected and then OK	05:35:00	06:00:00	to be checked
10	OHP	CO-34	Reported RED. OLR acted	Reset done	02:45:00	02:50:00	
11	OHP	TT-4 ON CO-22	Reported position sensor indication not coming. Found cable cut.	cable reconnected and made OK	03:35:00	03:50:00	
12	OHP	WOBR ON CO-6A	LT not working. Due to brake problem. M-1 tripped	Reset done and brake adjustment done	04:10:00	04:20:00	
13	OHP	CO-26	Reported RED. OLR acted	Reset done	04:30:00	04:45:00	

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 28/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	LC-19	I/C-2 tripped.	pump house-10 and cc-55 T/E lighting made off. Reset done and breaker made ON	22:40:00	22:50:00	to be checked further
15	CHP	SCR-9 ON CC-104	Slew not working. Checked and found MCCB tripped	Made ON and found OK.	00:00:00	00:20:00	
16	CHP	SCR-2 ON CC-33	PCRD drum sensor acted three times	Reset done and made OK	00:50:00 02:35:00 04:40:00	01:10:00 02:50:00 05:00:00	
17	CHP	CC-46	Overload acted	Reset done	04:20:00	04:30:00	
18	WT	CO-3	Overload acted	Reset done	05:35:00	05:40:00	