



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 30/08/2026

Shift: A

Incharge(s): G Eswara Rao,K SANKARA RAO

| Sl No | Area | Equipment        | Problem                                                   | Action                                                       | From     | To       | Remarks |
|-------|------|------------------|-----------------------------------------------------------|--------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | CO-25            | OLR ACTED                                                 | RESET DONE                                                   | 07:10:00 | 07:15:00 |         |
| 2     | OHP  | RSCO-6A (C)DRIVE | OLR ACTED                                                 | RESET DONE                                                   | 10:45:00 | 10:50:00 |         |
| 3     | OHP  | RCO-6A           | OLR ACTED                                                 | RESET DONE                                                   | 11:25:00 | 11:30:00 |         |
| 4     | CHP  | CC-58            | CURRENT SP FAULT TRIP                                     | RESET DONE                                                   | 12:25:00 | 12:40:00 |         |
| 5     | CHP  | CC-52            | MPD TRIP (FEEDING CONVEYOR STOP)                          | RESET DONE                                                   | 13:00:00 | 13:05:00 |         |
| 6     | CHP  | CC-54            | REPORTED BRS NOT HEALTHY FOUND GLASS FUSE BLOWN IN MODULE | GLASS FUSE REPLACED THAN OK                                  | 11:15:00 | 11:30:00 |         |
| 7     | CHP  | CC-40 SCR-7      | LUFF NOT WORKING MPR TRIP                                 | RESET DONE                                                   | 09:30:00 | 09:40:00 |         |
| 8     | CHP  | CO-111           | BRS ACTED                                                 | RESET DONE                                                   | 07:50:00 | 08:00:00 |         |
| 9     | CHP  | CC-40 SCR-7      | LUFF NOT WORKING FOUND MCCB AUX BLOCK PROBLEM             | AUX BLOCK REPLACED THAN OK                                   | 10:30:00 | 10:45:00 |         |
| 10    | CHP  | CC-36 S-1        | LT M-1 OLR ACTED                                          | RESET DONE                                                   | 11:25:00 | 11:40:00 |         |
| 11    | CHP  | CC-36 S-1        | B/C ZSS PROBLEM                                           | ZSS MODULE SPEED ADJUSTED THAN OK                            | 11:25:00 | 11:40:00 |         |
| 12    | WT   | OT-1             | DRIVE-2 OCA FAULT TRIP CHECKED AND FOUND M-2 BURNT        | MOTOR REPLACED DIRECTION CHECKED AND CLEARANCE GIVEN THAN OK | 09:40:00 | 14:20:00 |         |
| 13    | IOSA | OC-14A           | REPORTED HEALTHY STOP                                     | PULL CHORD HARD-WARE BYPASSED THAN OK                        | 09:50:00 | 10:10:00 |         |