



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/08/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Reported tripped	OLR acted.Reset done	16:30:00 20:40:00	16:35:00 20:50:00	
2	OHP	BRC on CO-32	B/C not running	E-stop acted outside operator cabin.Released and tested okay	14:43:00	14:55:00	
3	OHP	TBS on CO-5A	LT not taking place	PCRD tension acted due to mechanical chain got cut.Cable found zigzag and outside drum.Cable unwinding done and made free and loop provided due to mechanical chain problem	20:30:00	20:45:00	Two joints insulation to be provided
4	OHP	CO-6A	BRS bypassed	Sensor cable changed BRS tested and kept in line	16:40:00	17:10:00	
5	CHP	CC-58	Reported tripped	OLR acted.Reset done	20:50:00	21:10:00	
6	WT	OT-5	Wagon count not showing in OCR-2	Checked and found schneider output is there but contact high not there.Cable traced and found 24 V relay contact not making and high missing in GE rack in LC-9.Relay contact bypassed and high provided and tested okay	18:18:00	20:00:00	