



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

#### ELECTRICAL SHIFT REPORT

Date: 24/09/2026

Shift: B

Incharge(s): Amit Roy

| Sl No | Area | Equipment     | Problem                                              | Action                                                                                      | From                 | To                   | Remarks                             |
|-------|------|---------------|------------------------------------------------------|---------------------------------------------------------------------------------------------|----------------------|----------------------|-------------------------------------|
| 1     | OHP  | CO-29         | Unhealthy. OLR acted                                 | Reset done                                                                                  | 20:00:00             | 20:20:00             |                                     |
| 2     | OHP  | WOBR on CO-26 | Luffing not working. MPCB tripped                    | Reset done                                                                                  | 17:30:00             | 17:45:00             |                                     |
| 3     | OHP  | TBS on CO-7A  | Spark observed at the cable tray near operator cabin | Damaged cable part removed and proper jointing done                                         | 20:30:00             | 21:30:00             | No delay                            |
| 4     | OHP  | CO-111        | Reported tripped                                     | OLR acted.Reset done                                                                        | 15:15:00<br>15:25:00 | 15:25:00<br>15:35:00 |                                     |
| 5     | OHP  | WOBR on CO-6A | Interlock ZSS                                        | Probe changed and tested okay                                                               | 18:00:00             | 19:00:00             | NO delay as machine was in shutdown |
| 6     | OHP  | VS-2          | Reported tripped                                     | OLR acted.Reset done                                                                        | 21:40:00             | 21:45:00             |                                     |
| 7     | OHP  | CO-5          | Cable lug damaged while terminating                  | After alignment during motor termination one phase lug got damaged.Replaced and tested okay | 21:10:00             | 21:30:00             | No delay                            |
| 8     | CHP  | CO-2          | ZSS acted                                            | Due to belt piece hanging.Material stuck up inside cage                                     | 18:50:00             | 19:10:00             | Infomed to operation                |
| 9     | CHP  | CC-104 SCR-9  | LT not taking place                                  | Drive tripped.Reset done                                                                    | 19:30:00             | 19:45:00             |                                     |
| 10    | CHP  | CC-45         | ZSS acted                                            | Probe got directed.Probe directed                                                           | 20:55:00             | 21:20:00             |                                     |
| 11    | WT   | OC-1A         | ZSS acted                                            | Due to jamming                                                                              | 15:15:00             | 15:35:00             |                                     |