वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 30/10/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Reported tripped	OLR acted.Reset done	07:55:00	08:05:00	
2	OHP	CO-10A	BSS acted	BSS handle fell down.New handles installed and tested okay	09:40:00	09:50:00	
3	OHP	CO-16	Reported tripped	OLR acted.Reset done	13:10:00	13:15:00	
4	OHP	WOBR on CO-29	Luffing not taking place	Due to heavy load on B/C. Load cleared and tested okay	13:35:00	13:50:00	No electrical problem
5	CHP	Cc-25 on CC-37	Indication not coming	Bypass wire loose at I/O rack.Tightened and tested okay	11:20:00	11:30:00	
6	CHP	SCR-9 on CC-104	Slew and luff not working	Slew pump cooler fan tripped.Made on and tested okay Luff not taking place due to bucket stuck in coal	08:10:00	09:40:00	
7	CHP	S-3 on CC-112	B/C not running	Tripped on current sp fault.Reset done	10:15:00	10:25:00	
8	CHP	CC-51	MPD tripped	Reset done(3 times)	08:15:00	10:20:00	
9	CHP	CC-52	MPD tripped	Reset done(4 times)	08:20:00	10:10:00	