वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 29/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Reported RED. OLR acted	Reset done	00:20:00	00:30:00	
2	OHP	CO-29	Reported RED. OLR acted	Reset done	03:45:00	03:50:00	
3	OHP	CO-14B	OLR acted	Reset done	04:45:00	05:00:00	
4	OHP	WOBR ON CO-29	LT not working. M-4 OLR acted	Reset done	05:15:00	05:30:00	
5	CHP	CC-131	motor tripped on ground fault. Y-phase to Ground meggar value found to be zero.	cable traced and checked for any damage. No visible damage found as of now.	01:20:00	06:00:00	pending. To be checked further
6	CHP	SCR-2 ON CC-33	B/C not running in stacking mode. Found TUL c/s not healthy. Made bypass.	Slew 30 deg limits are also not coming. Slew done and made OK	22:30:00	23:00:00	Bypass to be removed
7	CHP	SCR-10 ON CC-105	B/C not running in reclaiming mode. Signal missing.	LT done and made OK	02:35:00	02:45:00	
8	CHP	SCR-5 ON CC-32	LT not working. Found PCRD cable fell down.	Rewinding done and made OK	03:30:00	03:45:00	
9	CHP	CC-219	Overload acted	Reset done	03:30:00	03:40:00	
10	CHP	CC-45	ZSS acted. ZSS found to be OK. Tail pulley jamming observed and belt is not rotating freely.	Informed to operation	04:20:00	04:35:00	No electrical delay
11	WT	AF-6	Tripped on ground fault three times. motor IR value checked and found OK.	Motor earthing cable found to be not connected. connected properly and local trail run taken. Found OK	01:35:00	02:05:00	