



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/09/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VS-5A	OLR ACTED. VS BEARING PROBLEM	RESET DONE	07:30:00	07:40:00	
2	OHP	CO-34	OLR ACTED	RESET DONE	07:50:00	07:55:00	
3	OHP	CO-50	TRIPPED ON OLR	RESET DONE	08:55:00	09:10:00	
4	OHP	RBF-2A	REPORTED STOPPING ON ZSS FOUND NO ELECTRICAL PROBLEM (MATERIAL JAMMING)	INFORMED TO OPERATION	08:10:00	08:30:00	
5	OHP	CO-48	OLR ACTED	RESET DONE	12:05:00	12:15:00	
6	OHP	RSCO-2A (C DRIVE)	TRIPPED ON OLR	RESET DONE	12:40:00	12:50:00	
7	OHP	TBS ON CO-5A	reported bc on fb signal missing. BC stopping on ZSS.	changed to spare Fatek PLC at OCR. to be observed further. BC ZSS checked no problem found.	06:00:00	07:00:00	
8	OHP	TBS ON CO-5A	REPORTED LT NOT TAKING PLACE FOUND PCRD CABLE OVER LAPPING	PCRD CABLE PROPER LAYING WITH MECHANICAL	09:15:00	09:45:00	
9	CHP	CC-27	REPORTED STOPPING ON ZSS CHECKED AND FOUND ZSS PROBE DAMAGED	ZSS PROBE REPLACED WITH NEW ONE THAN OK	11:00:00	11:10:00	
10	CHP	CC-109	BRS NOT RESET FOUND BRS SENSORS DISTURBED	SENSORS ADJUSTED THAN OK	06:30:00	06:45:00	
11	CHP	CC-36 SCR-3	LT NOT TAKING PLACE FOUND DRIVE TRIP	RESET DONE	13:05:00	13:15:00	