



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 24/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

| Sl No | Area | Equipment            | Problem                                    | Action                                                                                | From                 | To                   | Remarks  |
|-------|------|----------------------|--------------------------------------------|---------------------------------------------------------------------------------------|----------------------|----------------------|----------|
| 1     | OHP  | TIS-6 on co-29       | TIS stopping on ZSS fault                  | Probe problem, replaced and tested.,                                                  | 08:15:00             | 08:40:00             |          |
| 2     | OHP  | VF-17 CHP side motor | motor shaft broken.                        | motor replaced with spare and trail run taken, found ok.                              | 08:00:00             | 11:15:00             |          |
| 3     | OHP  | CO-67                | reported failed to start                   | RL-1 Sliding contact was loose, cable loop given from module to spare TB and checked. | 11:40:00             | 12:25:00             |          |
| 4     | OHP  | CR-3                 | tripped on overcurrent                     | Jamming found, cleared and restarted later                                            | 07:40:00             | 07:55:00             |          |
| 5     | OHP  | co-26                | olr acted                                  | reset done                                                                            | 07:10:00             | 07:20:00             |          |
| 6     | OHP  | TBS-2 ON co-20       | LT not taking place                        | M2 MPCB tripped due to track jamming. cleared and reset done                          | 10:15:00             | 10:30:00             |          |
| 7     | OHP  | brc-3 on co-33m      | LT not taking place                        | VFD tripped on OL fault, reset done.                                                  | 11:30:00             | 11:40:00             |          |
| 8     | OHP  | co-7a                | stopped on ZSS fault                       | zss is being checked.                                                                 | 13:45:00             | 14:00:00             |          |
| 9     | OHP  | co-10                | reported drive not healthy                 | DMPR was in COM. fault , power recycled.                                              | 12:00:00             | 12:20:00             | no delay |
| 10    | CHP  | scr-1 on cc-31       | bc not starting, slew 30degree limit acted | switch reset done                                                                     | 10:00:00             | 10:20:00             |          |
| 11    | CHP  | scr-3 on cc-37       | bc not starting, tripped on Curt Sp fault  | reset done                                                                            | 11:10:00             | 11:20:00             |          |
| 12    | CHP  | scr-7 on cc-40       | bc not starting                            | communication problem with CCR, LT done.                                              | 12:10:00<br>13:10:00 | 12:30:00<br>13:35:00 |          |
| 13    | CHP  | cc-40                | tripped on Curt Sp fault                   | reset done                                                                            | 12:15:00             | 12:20:00             |          |