वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 23/10/2026

Shift: A

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | TBS ON CO-22 | LT not working. Found PCRD cable got struck up due to old belt piece lying. | Removed the cable from obstruction and given clearance | 07:00:00 | 07:15:00 | |
| 2 | OHP | TBS ON CO-19 | Boom conveyor not running. Found Emergency operated | Released and made OK | 07:30:00 | 07:40:00 | |
| 3 | OHP | TBS ON CO-21 | LT not working. PCRD MPCB tripped. Reset done | PCRD drum tied with rope and informed to mechanical | 08:45:00 | 09:00:00 | |
| 4 | OHP | TBS ON CO-5A | Boom conveyor tripped due to overload | Reset done | 10:05:00 | 10:10:00 | |
| 5 | OHP | CO-25 | Overload acted | Reset done | 10:15:00 | 10:25:00 | |
| 6 | OHP | CO-26 | Overload acted | Reset done | 11:20:00 | 11:30:00 | |
| 7 | OHP | BRC ON CO-32 | Bucket wheel not rotating. Found stone struck up | Informed to mechanical | 11:20:00 | 11:35:00 | No electrical delay |
| 8 | OHP | TBS ON CO-7A | LT not working due to drive trip | reset done and Luffing limit switch tied with rope for material cleaning near trailer unloader | 10:45:00 | 11:00:00 | To be kept in circuit |
| 9 | CHP | SCR-5 ON CC-32 | BC not running. Overload tripped and found coal jamming at chute area. | reset done. Material cleaned by operation and made OK | 09:40:00 | 10:10:00 | No electrical delay |
| 10 | CHP | SCR-10 ON CC-105 | Signal missing in reclaiming mode. | LT done and made OK | 10:00:00 | 10:10:00 | |
| 11 | CHP | CC-51 | MPR acted to stop feeding conveyor | Reset done | 11:40:00 | 11:50:00 | |
| 12 | CHP | CC-203 | Overload acted | reset done | 06:15:00<br>13:00:00 | 06:20:00<br>13:05:00 | |
| 13 | CHP | CC-29 | Overload acted | Reset done | 09:15:00 | 09:20:00 | |

वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 23/10/2026 Shift: A

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 14 | CHP | CC-15 | Overload acted | Reset done | 13:05:00 | 13:10:00 | |
| 15 | CHP | CC-201 | Overload acted | Reset done | 06:15:00 | 06:20:00 | |
| 16 | CHP | CC-7,8,9,12 ,13,14 | Became Red. Found CM-6 Voltas breaker tripped when CC-9 started. | CC-9 power isolated, CC-9 panel outgoing flash observed. Voltas breaker changed with repaired one. Remaining conveyors made OK. | 11:40:00 | 12:25:00 | |
| 17 | WT | OT-5 | Not rotating. Found Outhaul sensor malfunctioning. MCC emergency stop healthy not coming. Speed reference became zero | Outhaul sensor connection removed, MCC Emergency bypassed in program and reference given. Then OK | 07:20:00 | 07:55:00 | |