



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/10/2026

Shift: C

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Reported tripped	OLR acted.Reset done	23:20:00	23:30:00	
2	OHP	WOBR on CO-6A	Slewing speed increasing suddenly	No electrical problem	00:00:00	00:15:00	Informed to mechanical
3	OHP	BRC on CO-32	LT not taking place	PCRD tension acted.Released	02:05:00	02:20:00	
4	OHP	VS-2	Reported tripped	OLR acted.Reset done	02:20:00	02:30:00	
5	OHP	CO-10 A	Reported tripped	OLR acted.Reset done	05:25:00	05:35:00	
6	OHP	CO-13A to RSCO-6A,C O-14B to CO-20	Chute vibrator not working	Common high fuse blown at I/O rack.Replaced and tested okay	00:30:00	01:00:00	
7	OHP	CC-33 SCR-2	Slewing not taking place	Left limit switch stuck.Made free	23:07:00	23:20:00	
8	CHP	Cc-131	Reported tripped	OLR acted.Reset done	00:40:00	00:45:00	
9	CHP	CC-125	Reported tripped	OLR acted.Reset done	02:55:00	03:00:00	
10	CHP	CC-112 S-3	B/C not running	ZSS probe wire got cut.Rejoint done and tested okay	00:15:00	00:35:00	
11	CHP	CC-109	ZSS acted	Belt overload.ZSS acting	22:40:00	22:50:00	NOT an electrical problem
12	IOSA	FLS WOBR	Lt not taking place	M-4 OLR acted due to track jamming.Jamming cleared and drive OVA fault tripping cleared by changing DBU settings	05:00:00	06:00:00	