



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/06/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-53	ZSS acting	Probe cable cut.Rejoint done	19:35:00	19:55:00	
2	OHP	CO-29	Reported tripped	OLR acted.Reset done	19:50:00	20:00:00	
3	OHP	CO-29	BRS acting	Neutral missed at BRS module.wire found came out of CJB.connected and tested okay	17:50:00	18:10:00	
4	OHP	WOBR on CO-29	LT not taking place	LT changed from DOL to Drive mode and tested okay	18:10:00	18:25:00	
5	OHP	BRC ON CO-8A	CT not taking place	MCCB in OFF condition.Made on and tested okay	19:35:00	19:55:00	
6	CHP	CC-51	MPD tripped	Reset done	20:55:00	21:00:00	
7	CHP	CC-125	Reported tripped	OLR acted.Reset done	19:00:00 19:50:00	19:10:00 19:55:00	
8	CHP	Cc-33 SCR-2	Reported no operations taking place	Control fuse burnt at I/O rack.Replaced and tested okay	19:50:00	20:30:00	
9	CHP	Cc-44	Reported tripped	OLR acted.Reset done	20:00:00	20:15:00	
10	CHP	Cc-201	Reported tripped	OLR acted.Reset done	14:40:00	14:45:00	
11	CHP	CC-21 (C/D)	Reported tripped	OLR acted.Reset done	14:50:00	14:55:00	
12	CHP	Cc-29	ZSS acting	Cage stuck with stone.removed and tested okay	16:10:00	16:15:00	
13	CHP	Cc-28	Reported tripped	OLR acted.Reset done	16:20:00	16:25:00	
14	CHP	CC-203	Reported tripped	OLR acted.Reset done	18:20:00	18:24:00	
15	CHP	Cc-203	ZSS acting	Due to mechanical fluid coupling problem	18:35:00	18:45:00	Informed to mechanical



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/06/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
16	WT	Af-5	Reported drive not running	Checked and found drive DC output not generating. Drive replaced with spare and control card replaced with old and trial taken and tested okay	18:55:00	21:45:00	
17	WT	CP-4	Reported tripped	Breaker tripped. Made on	16:55:00	17:05:00	