



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/07/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	Reported power failure	LBDS-4 11KV I/C-2 no power from TPP	ALL LC's in CHP,OHP,Tipler and IOSA LT side I/C-1 and buscoupler made on and power restored	21:00:00	22:00:00	
2	OHP	WOBR on CO-29	Luffing not taking place	OLR acted.Reset done	18:00:00	18:10:00	
3	CHP	CC-106 SCR-9	Luffing not working	Checked and found pump main solenoid not picking up.Fuse blown at I/O.Fuse replaced and tested okay	19:00:00	20:00:00	
4	CHP	CC-31	B/C not running	30 degree limit acted.Released and tested okay	19:20:00	19:35:00	
5	CHP	CC-51	MPD tripped	Reset done(3 times)	17:20:00	20:05:00	
6	CHP	CC-52	MPD tripped	Reset done(4 times)	17:15:00	19:00:00	
7	CHP	CC-54	Reported tripped	OLR acted.Reset done(2 times)	17:20:00	17:30:00	
8	WT	OT-5	Reported not rotating	Limit switches 5 and 8 got stuck up.Bypassed at CJB.	16:00:00	17:00:00	
9	WT	OT-5	Reported not healthy	Power restored in LC and CPU interchanged from redundancy module and communication restored and tested okay	22:00:00	22:30:00	Communication restored at 12.00 PM