



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 21/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on co 21	LT not working,M1 OLR acted,jamming	reset and informed operation	22:40:00	23:00:00	
2	OHP	TBS on CO 5A	LT not working,M1 and M2 OLR acted due to track jamming	informed operation,reset	03:55:00	04:10:00	
3	CHP	CC 54	motor tripped on OLR	reset	23:05:00	23:10:00	2 times
4	CHP	CC 53	TT position not showing on RG2	TT position properly ,signal ok	23:15:00	23:35:00	
5	CHP	CC 31 SCR1	slew not working,left limit acted due to coal jamming	informed operation	22:45:00	22:55:00	
6	CHP	CC 48	BRS not getting reset,sensor receiver side plug side loose connection	sensor connected properly	22:35:00	23:55:00	
7	CHP	CC 37 SCR3	slew not working,OIL level low	informed mechanical	01:10:00	01:20:00	
8	CHP	CC 39 SCR9	LT not working ,M2 OLR acted	reset	03:45:00	03:55:00	
9	CHP	CC 33 SCR2	LT not working,PCRD drum sensor acted	reset	04:30:00	04:40:00	
10	CHP	CC 107	mpd acted	reset	03:30:00	03:35:00	