



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/07/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	OLR ACTED	RESET DONE	06:40:00	06:45:00	
2	OHP	BRC ON CO-32	REPORTED B/C NOT RUNNING CHECKED AND FOUND CABIN SIDE E/STOP ACTED	RELEASED THAN OK	07:20:00	07:30:00	
3	OHP	CO-26	OLR ACTED (2TIMES)	RESET DONE	08:00:00 11:10:00	08:05:00 11:20:00	
4	OHP	TT-3	REPORTED TT-3 ON CO-22 POSITION INDICATION PROBLEM CHECKED AND FOUND GLASS FUSE BLOWN DUE TO EARTH FAULT	RECTIFIED EARTH FAULT AND FUSE REPLACED THAN INDICATION OK	07:40:00	08:00:00	
5	CHP	CC-58 ON TT	REPORTED LT NOT TAKING PLACE FOUND MPCB FAILD	REPLACED WITH NEW ONE THAN OK	11:15:00	12:00:00	
6	CHP	CC-54	OLR ACTED	RESET DONE	08:15:00	08:20:00	
7	CHP	CC-215	OLR ACTED	RESET DONE	07:15:00	07:25:00	
8	IOSA	OC-7B	REPORTED STOPPING ON HEALTHY CHECKED AND FOUND NO PROBLEM	CLEARANCE GIVEN THAN OK	07:55:00	08:11:00	
9	IOSA	OC-7B	REPORTED STOPPING ON FAIL TO START CHECKED ALL THINGS NO PROBLEM FOUND	CHECKED AND TESTED	07:15:00 11:55:00	08:00:00 13:05:00	
10	IOSA	OC -7B	FAIL TO START	SERVICE POSITION CONTACT PROBLEM .. FIXED .. MPR PROBLEM ... BYPASSED FOR TIPLING	11:55:00	13:00:00	MPR TO BE CHANGED