



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 27/07/2026

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment      | Problem             | Action                                                                                                                                                                               | From     | To       | Remarks               |
|-------|------|----------------|---------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|-----------------------|
| 1     | OHP  | RSCO-10A(C/D)  | Reported tripped    | OLR acted.Reset done                                                                                                                                                                 | 18:30:00 | 19:00:00 |                       |
| 2     | OHP  | TIS on CO-29   | ZSS acting          | Wrong complaint                                                                                                                                                                      | 15:05:00 | 15:20:00 |                       |
| 3     | OHP  | BRC on CO-32   | B/W's not running   | Oil temperature high.Oil cooler MPCB in off condition.After temperature cooled down pump ran and tested okay                                                                         | 19:15:00 | 19:30:00 |                       |
| 4     | OHP  | CO-26          | Reported tripped    | OLR acted.Reset done                                                                                                                                                                 | 20:25:00 | 20:35:00 |                       |
| 5     | OHP  | TT-2           | CJD not healthy     | Wire got cut.Rejoint done and tested okay                                                                                                                                            | 21:27:00 | 21:33:00 |                       |
| 6     | OHP  | OP-9           | Reported not moving | Outhaul proxy sensor not healthy.Bypassed and tested okay                                                                                                                            | 21:38:00 | 21:40:00 |                       |
| 7     | CHP  | SCR-1 on CO-31 | B/c stopping        | No problem found.given clearance                                                                                                                                                     | 20:10:00 | 20:30:00 |                       |
| 8     | CHP  | CC-28 TT       | CJD acted           | Due to material jamming                                                                                                                                                              | 21:20:00 | 21:30:00 | Informed to operation |
| 9     | IOSA | OC-7B          | MPR Relay bypassed  | Checked and found MPR displaying no voltages.Bus pt voltages found okay at MCB and relay terminals also voltages found okay.Relay inserted properly and tested okay.MPR kept in line | 18:00:00 | 20:00:00 |                       |