वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 24/10/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | TBS on co 22 | all drive not working,control mcb tripped | made it on | 22:45:00 | 23:00:00 | |
| 2 | OHP | rsco 6A(c) | olr acted | reset | 22:54:00 | 23:00:00 | |
| 3 | OHP | co 26 | olr acted | reset | 00:10:00 | 00:20:00 | |
| 4 | OHP | CO 34 | BRS and emergency acted,cable got cut and earthed b/w CJB to near motor,fuse blown | fuse replaced,cable checked from common cjb to BRS CJB ,brs bypassed in i/o rack | 23:50:00 | 00:40:00 | cable to be changed |
| 5 | CHP | CC 52 | mpd acted | reset | 04:40:00 | 04:45:00 | |
| 6 | CHP | CC 15 | olr acted | reset | 23:10:00 | 23:15:00 | 3 times |
| 7 | CHP | CC 35 stk2 | LT not working,m5 tripped | made it on | 01:15:00 | 01:25:00 | |
| 8 | CHP | CC 31 | motor tripped due to olr | reset | 01:20:00 | 01:25:00 | |
| 9 | CHP | CC 104 scr 9 | luff not working,pump is in off | made it on | 02:30:00 | 02:40:00 | |
| 10 | WT | CP 4 | rev not moving,RLS acted | released RLS | 23:00:00 | 23:10:00 | |
| 11 | WT | CP 4 | FWD not moving,FWD LS acted,LS problem | F LS bypassed in cjb | 01:30:00 | 01:45:00 | FLS to be changed |