वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 08/11/2026

Shift: B

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | RSCO-6A | Overload acted | Reset done | 17:00:00 | 17:10:00 | |
| 2 | OHP | VF-10A | Overload acted | Reset done | 17:55:00<br>21:05:00 | 18:00:00<br>21:15:00 | |
| 3 | OHP | BRC-1 ON CO-31 | B/C tripped on overload | Reset done | 14:10:00 | 14:20:00 | |
| 4 | OHP | CO-26 | overload acted | reset done | 15:00:00 | 18:50:00 | three times |
| 5 | OHP | DB-1 | Reported RED. found glass fuse loose in CJB | Properly connected and found OK | 19:00:00 | 19:15:00 | |
| 6 | CHP | CC-54 | Overload tripped | Reset done | 19:20:00 | 19:30:00 | two times |
| 7 | CHP | CC-131 | overload tripped | Reset done | 18:25:00 | 18:30:00 | |
| 8 | CHP | SCR-5 ON CC-32 | B/C tripped on overload | reset done | 15:40:00 | 15:50:00 | |
| 9 | CHP | RECL-1 ON CC-36 | LT not operating. Found over tension limit switch stuck up. | switch cleaned and made free | 16:00:00 | 16:15:00 | |
| 10 | CHP | SCR-9 ON CC-104 | TUL chute sensor acted. found jamming | informed to operation | 20:35:00 | 20:45:00 | |
| 11 | CHP | CC-26A | overload acted | Reset done | 19:30:00 | 19:40:00 | |
| 12 | CHP | CC-110 | ZSS acted. found material jamming | Informed to operation. after cleaning found OK | 19:50:00 | 20:00:00 | |
| 13 | WT | OC-1A, OAF-1A,OAF-2A | Became unhealthy. | LC-9 PLC I/O rack recycle done and made OK | 21:25:00 | 21:30:00 | |

वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 08/11/2026

Shift: B

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 14 | WT | CP-1 | Drive-6 tripping on OCA. Found motor R-phase lug got cut. | Drive feedback bypassed for rake completion. after rake completion, Re crimping and proper termination done and checked OK | 15:15:00 | 15:30:00 | |
| 15 | IOSA | BRC ON OC-15A | Bucket wheel-2 stopping after running for 10 sec. ZSS probe found to be faulty | Bypassed and checked OK. | 20:15:00 | 20:35:00 | probe to be changed and checked |