



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 25/05/2026

Incharge(s): Lal Singh

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-7A TBS	CHUT SENSOR NOT HEALTHY	RESET DONE	15:05:00	15:20:00	
2	OHP	WBR ON CO -29	ALL DRIVES NOT WORKING .. DOWN EM ACTED	LUFF UP DONE THEN KEPT IN CKT	17:30:00	17:40:00	
3	OHP	CO-26	OLR ACTED	RESET DONE	18:50:00	18:55:00	
4	OHP	BRC -4 ON CO -8A	PUMP STOPPING ON CHARGE PRESSER P-1	NO ELECTRICAL PROBLEM	20:45:00	20:55:00	
5	CHP	CC-102	POSITION SIGNAL ON CC-105 NOT COMING FUSE BLOWN	FUSE REPLACED THEN OK	14:50:00	15:15:00	
6	CHP	CC-102	CHUT SENSOR NOT HEALTHY	C/S OK IN FIELD BUT NOT REACHING IN IO RACK ... BYPASSED	15:15:00	15:45:00	TO BE CHECKED
7	CHP	CC-52	MPD TRIP	RESET DONE	16:05:00	16:10:00	
8	CHP	CC-114	NOT RUNNING .. 3TF-53 CONTACTOR GETTING STUCK AND CONTROL MCB TRIPPING	COIL CONNECTIONS TIGHTENED AND CONTACTOR MADE FREE THEN TESTED OK	19:20:00	20:00:00	