वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 23/10/2026

Shift: A

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-22	LT not working. Found PCRD cable got struck up due to old belt piece lying.	Removed the cable from obstruction and given clearance	07:00:00	07:15:00	
2	OHP	TBS ON CO-19	Boom conveyor not running. Found Emergency operated	Released and made OK	07:30:00	07:40:00	
3	OHP	TBS ON CO-21	LT not working. PCRD MPCB tripped. Reset done	PCRD drum tied with rope and informed to mechanical	08:45:00	09:00:00	
4	OHP	TBS ON CO-5A	Boom conveyor tripped due to overload	Reset done	10:05:00	10:10:00	
5	OHP	CO-25	Overload acted	Reset done	10:15:00	10:25:00	
6	OHP	CO-26	Overload acted	Reset done	11:20:00	11:30:00	
7	OHP	BRC ON CO-32	Bucket wheel not rotating. Found stone struck up	Informed to mechanical	11:20:00	11:35:00	No electrical delay
8	OHP	TBS ON CO-7A	LT not working due to drive trip	reset done and Luffing limit switch tied with rope for material cleaning near trailer unloader	10:45:00	11:00:00	To be kept in circuit
9	CHP	SCR-5 ON CC-32	BC not running. Overload tripped and found coal jamming at chute area.	reset done. Material cleaned by operation and made OK	09:40:00	10:10:00	No electrical delay
10	CHP	SCR-10 ON CC-105	Signal missing in reclaiming mode.	LT done and made OK	10:00:00	10:10:00	
11	CHP	CC-51	MPR acted to stop feeding conveyor	Reset done	11:40:00	11:50:00	
12	CHP	CC-203	Overload acted	reset done	06:15:00 13:00:00	06:20:00 13:05:00	
13	CHP	CC-29	Overload acted	Reset done	09:15:00	09:20:00	

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 23/10/2026 Shift: A

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	CC-15	Overload acted	Reset done	13:05:00	13:10:00	
15	CHP	CC-201	Overload acted	Reset done	06:15:00	06:20:00	
16	CHP	CC-7,8,9,12 ,13,14	Became Red. Found CM-6 Voltas breaker tripped when CC-9 started.	CC-9 power isolated, CC-9 panel outgoing flash observed. Voltas breaker changed with repaired one. Remaining conveyors made OK.	11:40:00	12:25:00	
17	WT	OT-5	Not rotating. Found Outhaul sensor malfunctioning. MCC emergency stop healthy not coming. Speed reference became zero	Outhaul sensor connection removed, MCC Emergency bypassed in program and reference given. Then OK	07:20:00	07:55:00	