वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 27/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-22	All drives nor working. Control transformer fault	Hot blowing done for CTF-1,2. CTF-1 failed. Load given to CTF-1 and made OK	22:00:00	02:00:00	
2	OHP	WOBR ON CO-26	LT not working. Found M3, M6 tripped	Reset done	23:50:00	00:20:00	
3	OHP	WOBR ON CO-25	Slew not working. Drive tripped	Reset done	00:15:00	00:40:00	
4	OHP	TBS ON CO-7A	LT not working. Drive tripped	Reset done	00:30:00	00:50:00	
5	OHP	BRC ON CO-28	B/W-1 not running. Found fluid coupling side oil leakage	Informed to mechanical	02:40:00	03:00:00	
6	OHP	WOBR ON CO-26	Slewing not working.	Fault reset done and made OK	03:25:00	03:45:00	
7	OHP	CO-25	OLR acted	Reset done	05:40:00	05:50:00	
8	CHP	CC-37	MCCB tripped	Reset done	00:15:00	00:30:00	
9	CHP	CC-126	Belt sway acted.	Bypassed in I/O rack	01:10:00	01:30:00	
10	CHP	SCR-1 ON CC-31	B/C ZSS and Chute sensor acting	Bypassed	02:30:00	03:00:00	
11	CHP	CC-32	Drive end chute sensor bypassed	.	03:30:00	03:40:00	
12	CHP	SCR-2 ON CC-33	Modem not communicating. Checked and found modem power OK	To be checked further	03:40:00	04:10:00	pending
13	CHP	CC-125	ZSS acted complaint. Found neutral missing in module	Bypassed and given clearance	03:30:00	03:45:00	

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 27/10/2026 Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	SCR-7 ON CC-40	B/C not running. Overload acted	Reset done	03:40:00	03:55:00	
15	CHP	SCR-7 ON CC-40	Chute sensor acted	Bypassed	05:10:00	05:20:00	
16	CHP	LC-19	I/C-1 tripped.	Reset done	22:00:00 23:00:00	22:10:00 23:10:00	
17	CHP	LC-19	I/C-2 tripped due to PDB cable damaged at PDB due to LDB grounded at cc-52 tail end	Reset done	22:30:00	23:30:00	two times
18	CHP	CC-131	Belt sway and pullcord showing unhealthy. Found cable damaged	Bypassed and given clearance	04:50:00	05:45:00	
19	CHP	COB-5 PLC power failed	LC-5 incomer tripped.	Incomer power made ON and UPS reset done.	01:45:00	02:40:00	
20	WT	LC-2A MODEM	Modem not communicating with LC-1 modem.	Configured another modem and installed, but still no communication. Changed LC-1 modem also after configuration	22:01:00	01:25:00	
21	WT	OP-8	No movement. Found Modem Ok. But PLC not communicating	To be checked	03:10:00	04:00:00	pending
22	WT	OP-5	Not moving. D-1 Overload acted	Reset done	23:45:00	01:30:00	
23	WT	CT-1,2	LC-9 incomer-1 no power	bus-coupler made on	23:00:00	23:30:00	
24	WT	CT-1,2	Wagon sensors acting due to water	bypassed in program	23:00:00	23:30:00	
25	WT	CO-2	ZSS acting	Bypassed in I/O rack	02:00:00	02:15:00	
26	WT	CP-1	No movement. Communication fault	Power recycle done on both sides	05:30:00	05:45:00	

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 27/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
27	WT	CP-3	Power tripped in LC-10A	Breaker made on and made OK	05:30:00	05:45:00	