



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/07/2026

Shift: B

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TIS-2	POWER MCCB TRIP	MADE ON	15:20:00	15:30:00	
2	OHP	CO-26	OLR ACTED (2TIMES)	RESET DONE	17:15:00 19:50:00	17:20:00 19:55:00	
3	OHP	TBS-ON CO-22	LT NOT TAKING PLACE DRIVE TRIP	RESET DONE	21:20:00	21:25:00	
4	OHP	BRC ON CO-33M	REPORTED LT NOT TAKING PLACE PCRD O/T ACTED	RELEASED THAN OK	19:05:00	19:15:00	
5	CHP	CC-29 F/G	OLR ACTED	RESET DONE	14:15:00	14:20:00	
6	CHP	CC-130 ,CC-131	REPORTED NOT HEALTHY FOND STOP PB AND PC ACTED	RELEASED THAN OK	20:00:00	20:20:00	
7	CHP	CC-31 SCR-1	B/C NOT RUNNING SIGNAL MISSING	LT FW DIRECTION MOVE THAN OK	16:40:00	16:45:00	
8	CHP	CC-38	BRS ACTED FREQUENTLY	SENSOR CLEANED THAN OK	17:45:00	18:00:00	
9	WT	OP-9	NOT MOVING	EM ACTED ... RELEASED	15:00:00	15:10:00	
10	WT	OP-5	MOVING SLOW	COUPLING SENSOR BYPASSED	18:10:00	18:25:00	
11	IOSA	OC-7B	NOT HEALTHY .. VCB COIL FAILED .. HT FUSE BLOWN	FEEDER REPLACED .. HT FUSE REPLACED .. MOTOR MEGGER DONE FOUND OKSTILL NOT RUNNING .. CONTROL CKT CHECKEDRELAY (FOR FUSE HEALTHY) NC CONTACT PROBLEM ... CONTACT CHANGED AND TESTED .	15:40:00	17:40:00	