



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TIS-6 on co-29	TIS stopping on ZSS fault	Probe problem, replaced and tested.,	08:15:00	08:40:00	
2	OHP	VF-17 CHP side motor	motor shaft broken.	motor replaced with spare and trail run taken, found ok.	08:00:00	11:15:00	
3	OHP	CO-67	reported failed to start	RL-1 Sliding contact was loose, cable loop given from module to spare TB and checked.	11:40:00	12:25:00	
4	OHP	CR-3	tripped on overcurrent	Jamming found, cleared and restarted later	07:40:00	07:55:00	
5	OHP	co-26	olr acted	reset done	07:10:00	07:20:00	
6	OHP	TBS-2 ON co-20	LT not taking place	M2 MPCB tripped due to track jamming. cleared and reset done	10:15:00	10:30:00	
7	OHP	brc-3 on co-33m	LT not taking place	VFD tripped on OL fault, reset done.	11:30:00	11:40:00	
8	OHP	co-7a	stopped on ZSS fault	zss is being checked.	13:45:00	14:00:00	
9	OHP	co-10	reported drive not healthy	DMPR was in COM. fault , power recycled.	12:00:00	12:20:00	no delay
10	CHP	scr-1 on cc-31	bc not starting, slew 30degree limit acted	switch reset done	10:00:00	10:20:00	
11	CHP	scr-3 on cc-37	bc not starting, tripped on Curt Sp fault	reset done	11:10:00	11:20:00	
12	CHP	scr-7 on cc-40	bc not starting	communication problem with CCR, LT done.	12:10:00 13:10:00	12:30:00 13:35:00	
13	CHP	cc-40	tripped on Curt Sp fault	reset done	12:15:00	12:20:00	