वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 22/10/2026

Shift: A

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC ON CO-8A	Bucket wheel not running due to Air blast cooler not healthy	PLC side loose connection found. Tightness done	07:35:00	07:55:00	
2	OHP	CO-34	BRS not getting reset.	Found wrong complaint	09:25:00	09:40:00	
3	OHP	BRC ON CO-8A	Bucket wheels not running but pump is in ON condition. Operator has not operated Bucket Wheel start button	Informed to operation	09:00:00	09:20:00	
4	OHP	CO-6	BRS not getting reset. Found loose contact in module	Tightened and made OK	10:55:00	11:15:00	
5	OHP	TT-1	Not moving. Found MPCB tripped	Reset done	12:30:00	12:40:00	
6	CHP	CC-54	Overload acted	Reset done	10:35:00	10:40:00	
7	CHP	STK-2 ON CC-35	LT not working. Found M-2 tripped.	Reset done	10:15:00	10:30:00	
8	CHP	CC-125	BRS acting frequently. Found canopy damaged completely and obstructing BRS.	Kept in bypass and informed agency to rectify canopy	11:30:00	11:50:00	Bypass to be removed
9	CHP	CC-9	MCCB flash over occurred when conveyor started. Voltas breaker feeding to CM-6 also tripped. Found contactor one pole is internally short.	MCCB panel racked out. Voltas breaker is not closing. Spare voltas breaker racked in and given clearance.	07:10:00	08:15:00	Rectification is under progress
10	CHP	CC-28	Overload acted	Reset done	08:30:00 11:15:00	08:40:00 11:25:00	