



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/08/2026

Shift: A

Incharge(s): G Eswara Rao

| Sl No | Area | Equipment         | Problem                                                                                                            | Action                                                                                                                                | From                 | To                   | Remarks |
|-------|------|-------------------|--------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------|---------|
| 1     | OHP  | CO 26             | TRIPPED ON OLR twice                                                                                               | RESET DONE                                                                                                                            | 07:40:00<br>08:20:00 | 07:50:00<br>08:25:00 |         |
| 2     | OHP  | TIS 4 ON<br>CO 44 | NOT RUNNING/OLR ACTED AND CO 44 BELT OFFCENTREING and OBSTRUCTING THE TIS BELT                                     | RESET DONE AFTER MECH.ADJUSTMENT                                                                                                      | 07:10:00             | 07:25:00             |         |
| 3     | OHP  | CO 50             | TRIPPED ON OLR                                                                                                     | RESET DONE                                                                                                                            | 08:05:00             | 08:15:00             |         |
| 4     | OHP  | TBS ON CO 7A      | LT NOT TAKING PLACE/DRIVE NOT STARTING AND SHOWING LVO FAULT,                                                      | CHECKED AND FOUND POWER CONTACTOR O/G TERMINATION GOT LOOSE AND SELECTOR IN BYPASS MODE/ALL TERMINATIONS TIGHTEND,KEPT IN REMOTE MODE | 09:40:00             | 10:50:00             |         |
| 5     | OHP  | CO 10A            | ZSS ACTING/RETURN WIRE LOOSE IN ZSS MODULE TB                                                                      | ALL WIRES TIGHTEND IN TB THEN OK                                                                                                      | 11:05:00             | 11:30:00             |         |
| 6     | OHP  | TBS ON CO 19      | RIGHT LUFFING NOT WORKING /OLR ACTED                                                                               | RESET DONE                                                                                                                            | 11:10:00             | 11:20:00             |         |
| 7     | OHP  | BRC ON CO 8A      | NO DRIVES RUNNING/ACB TRIPPED                                                                                      | ACB MADE ON                                                                                                                           | 13:20:00             | 13:30:00             |         |
| 8     | CHP  | CC-12             | bss acted due to offcentering                                                                                      | bss adjusted on operation requirement and reset done                                                                                  | 09:45:00             | 09:55:00             |         |
| 9     | WT   | CP 1              | F/R NOT TAKING PLACE/COMMUNICATION FAULT                                                                           | RESET DONE                                                                                                                            | 07:15:00             | 07:55:00             |         |
| 10    | WT   | CP 4              | F/R NOT TAKING PLACE/ MICROLOGIC PLC in LC10A communication PROBLEM. Ethernet cable connected properly and tested. | RESET DONE                                                                                                                            | 09:45:00             | 10:40:00             |         |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/08/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment | Problem                            | Action                     | From     | To       | Remarks |
|-------|------|-----------|------------------------------------|----------------------------|----------|----------|---------|
| 11    | WT   | AF 4      | NOT RUNNING/DRIVE TRIPPED          | POWER AND CONTROL RECYCLED | 11:45:00 | 12:00:00 |         |
| 12    | WT   | OT 5      | F/R NOT TAKING PLACE/TOP LAMP LS 2 | KEPT BYPASS IN SCADA       | 12:20:00 | 12:30:00 |         |