



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/06/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	brc on co 8A	b/w 1 and 2 not running,solenoid coil plug having problem	temporary jointed	12:40:00	13:35:00	solenoid coil top plug to be replaced
2	OHP	BRC on co 33M	b/w 2 not running,olr atced	reset	09:00:00	09:15:00	
3	CHP	CC 32 SCR2	slew not working,drive tripped due to olr	reset	08:55:00	09:05:00	
4	CHP	CCC 31 SCR1	luff not working,due to OLR	reset	09:40:00	09:55:00	
5	CHP	CC 51	mpd tripped	reset	07:15:00	07:20:00	4 times
6	WT	AF 6	tripping in speed deviation fault	all parameter checked,found ok electrical side,motor run after decouple found motor run smooth	06:15:00	14:30:00	checking going on
7	WT	OP 7	no power, middle trolley line insulator punctured @col no 98-99	temporary insulation provided	11:40:00	12:05:00	
8	IOSA	OLD wobr on oc17A	Lt not working,PCRD OT acted	released	11:05:00	11:15:00	