



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 07/10/2026

Incharge(s): M Kailash

Shift: A

| Sl No | Area | Equipment      | Problem                                                          | Action                                                | From     | To       | Remarks                                 |
|-------|------|----------------|------------------------------------------------------------------|-------------------------------------------------------|----------|----------|-----------------------------------------|
| 1     | OHP  | CO-29          | Pullcord unhealthy. Found CJB field fuse blown.                  | Bypassed in CJB                                       | 09:00:00 | 09:15:00 | Informed to General shift               |
| 2     | OHP  | CO-25          | Overload acted                                                   | Reset done                                            | 09:15:00 | 09:22:00 |                                         |
| 3     | OHP  | CO-78          | Pullcord unhealthy.                                              | All pullcords acted and released. Then became healthy | 09:10:00 | 09:35:00 |                                         |
| 4     | OHP  | BRC ON CO-32   | LT not moving. PCRD tension acted                                | Released and made OK                                  | 12:35:00 | 12:45:00 |                                         |
| 5     | OHP  | BRC on CO-8A   | LT not working. Found M-1,3 tripped in drive 2 panel             | Reset done                                            | 10:05:00 | 10:20:00 |                                         |
| 6     | CHP  | CC-125         | Tripped on overload                                              | Reset done                                            | 09:00:00 | 09:05:00 |                                         |
| 7     | CHP  | CC-22          | Tripped on overload due to jamming                               | Reset done                                            | 11:20:00 | 11:30:00 |                                         |
| 8     | IOSA | WOBR ON OC-17A | LT drive tripping. Found track jamming and motors M-6,7 problem. | Motors isolated                                       | 06:00:00 | 07:15:00 | Track jamming and no electrical problem |