



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 03/05/2026

Shift: B

Incharge(s): Amit Roy

| Sl No | Area | Equipment      | Problem                  | Action                                                                          | From     | To       | Remarks                                                        |
|-------|------|----------------|--------------------------|---------------------------------------------------------------------------------|----------|----------|----------------------------------------------------------------|
| 1     | OHP  | RSCO-10A       | Chute sensor not working | Fuse blown.Replaced and tested okay                                             | 15:20:00 | 15:30:00 |                                                                |
| 2     | OHP  | CO-26          | Reported tripped         | OLR acted.Reset done                                                            | 18:05:00 | 18:12:00 |                                                                |
| 3     | OHP  | CO-35          | Reported not healthy     | E-stop stuck.Released and tested okay                                           | 15:10:00 | 15:20:00 |                                                                |
| 4     | OHP  | BRC on CO-28   | LT not taking place      | LT in Local.Kept in remote                                                      | 15:35:00 | 15:50:00 |                                                                |
| 5     | CHP  | SCR-7 on CC-39 | LT not taking place      | Drive tripped.Reset done                                                        | 17:20:00 | 17:30:00 |                                                                |
| 6     | CHP  | Cc-107         | Reported tripped         | OLR acted.Reset done                                                            | 17:45:00 | 17:55:00 |                                                                |
| 7     | CHP  | Cc-37 SCR-3    | LT not taking place      | PCRD cable zigzag due to guide problem                                          | 20:10:00 | 20:30:00 | Informed to mechanical. After adjustment cable winded properly |
| 8     | WT   | OT-3           | Reported tripped         | D-2 tripped.Reset done                                                          | 20:25:00 | 20:30:00 |                                                                |
| 9     | WT   | CT-2           | Inhaul tripped           | Reset done                                                                      | 15:25:00 | 15:30:00 |                                                                |
| 10    | IOSA | FLS WOBR       | LT not taking place      | PCRD overtension acted.Loop given and power kept off due to H/E side reclaiming | 20:10:00 | 20:20:00 | NO delay                                                       |