वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 11/11/2026

Shift: A

Incharge(s): Lal Singh

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | TBS ON COI -21 | R- LUFF OLR ACTED | RESET DONE | 12:58:00 | 13:10:00 | |
| 2 | OHP | TBS ON CO-7A | LT NOT WORKING | PCRD OT RELEASED THEN TESTED OK | 13:10:00 | 13:20:00 | |
| 3 | OHP | BRC ON CO-32 | ALL DRIVES NOT WORKING | ACB OFF ... MADE ON THEN OK | 13:25:00 | 13:35:00 | |
| 4 | OHP | BRC ON CO-28 | BC NOT RUNNING | EM STOP NOT COMING ... BYPASSED IN PANEL AND TESTED | 11:10:00 | 11:55:00 | TO BE KEPT IN CKT |
| 5 | OHP | WBR ON CO-26 | LUFF EM ACTED | LUFF DOWN AND LIMIT KEPT IN CKT AND TESTED | 12:15:00 | 12:30:00 | |
| 6 | OHP | CO-22 TBS | NO POWER ... PCRD CABLE PROBLEM | RECTIFIED BY DNW | 09:20:00 | 12:40:00 | |
| 7 | CHP | CC-203 FG | MPCB TRIPPED | MADE ON AND TESTED | 11:30:00 | 11:40:00 | |
| 8 | CHP | CC-131 | MPD TRIPPED 5 TIMES | RESET DONE | 11:00:00 | 13:00:00 | |
| 9 | CHP | CC-131 | TRIPPED | RESET DONE | 12:40:00 | 12:45:00 | |
| 10 | CHP | CC-108 | BRS NOT RESETTING | SENSOR CLEANING AND ALIGNMENT DONE THEN RESET | 09:22:00 | 09:35:00 | |
| 11 | CHP | CC-32 SCR-5 | LT NOT WORKING ... PCRD OT ACTED | RELEASED | 10:55:00 | 11:10:00 | |
| 12 | CHP | CC-40 SCR-7 | SIGNAL MISSING | POWER RECYCLED THEN OK | 13:15:00 | 13:30:00 | |
| 13 | WT | OT-5 | NOT ROTATING | BREAK RECTIFIER PROBLEM ... REPLACED AND TESTED | 06:00:00 | 07:10:00 | |