वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 09/11/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-50	OLR acted	Reset done	22:15:00	22:25:00	
2	OHP	VF-10A	OLR acted	Reset done	00:15:00	00:30:00	
3	OHP	CO-25	Overload acted	Reset done	01:30:00	01:40:00	
4	OHP	BRC ON CO-32	PCRD cable stick up to track fixture.	HT power made OFF and cable removed from track and HT power normalised	01:10:00	01:30:00	
5	OHP	TBS ON CO-21	LT not working. M-4 OLR acted	Reset done	04:00:00	04:10:00	
6	OHP	VF-5	Emergency not coming healthy. Found pushbutton damaged	Bypassed and given clearance	04:20:00	04:45:00	To be rectified
7	OHP	TBS ON CO-20	Left luff not working	.	04:20:00	04:30:00	wrong complaint
8	OHP	CO-51	DB position not showing on DB-3 and 5. Selector switch problem	Bypassed in I/O rack	04:35:00	05:10:00	to be rectified
9	CHP	STK-2 ON CC-32	LT not working. Found potentiometer in zero position	made OK	23:25:00	23:40:00	wrong operation
10	CHP	CC-215	Overload trip	reset done	02:50:00	03:00:00	
11	CHP	SCR-3 ON CC-106	Slew not working. checked and found oil pump damaged	informed to operation	00:35:00	00:45:00	
12	CHP	SCR-3 ON CC-106	LT not working. Drive tripped	Reset done	05:25:00	05:45:00	
13	CHP	CC-58	Tripped on CURT SP.	Reset done	23:15:00	23:35:00	
14	CHP	CC-131	overload tripped	Reset done	03:25:00	03:30:00	

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 09/11/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
15	WT	CT-1	Drive tripping on PGF-4 fault. checked in Brake Mode and found Brake is not releasing.	Checked panel side, rectifier side, found OK. coil continuity not coming from Brake panel. Found Brake supply cable melted at brake terminals. Temporary connection made and given clearance	04:00:00	05:10:00	