



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 17/08/2026

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment      | Problem             | Action                                                                                   | From                 | To                   | Remarks                           |
|-------|------|----------------|---------------------|------------------------------------------------------------------------------------------|----------------------|----------------------|-----------------------------------|
| 1     | OHP  | WOBR on CO-26  | LT not taking place | PCRD tension acted.Cable winded in drum and again tied with rope                         | 14:30:00             | 14:45:00             | Mechanical gearbox problem        |
| 2     | OHP  | CO-25          | Reported tripped    | OLR acted.Reset done                                                                     | 15:00:00             | 15:15:00             |                                   |
| 3     | OHP  | BRC on CO-30   | LT not working      | PCRD tension acted.Released and tested okay                                              | 18:45:00             | 18:55:00             |                                   |
| 4     | OHP  | CO-6A          | BRS malfunctioning  | Electronic BRS sensor cable found damaged.Electronic BRS bypassed.Mechanical JOD in line | 19:50:00             | 20:10:00             | Electronic BRS to be kept in line |
| 5     | CHP  | CC-52          | MPD tripped         | Reset done(2 times)                                                                      | 15:55:00<br>21:30:00 | 16:00:00<br>21:35:00 |                                   |
| 6     | CHP  | SCR-1 on CC-31 | Signal missing      | LT done and tested okay                                                                  | 20:10:00             | 20:20:00             |                                   |