# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 22/10/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | TBS on CO 20 | LT not working,due to M4 OLR | reset | 22:20:00 | 22:35:00 | |
| 2 | OHP | CO 25 | OLR acted | reset | 22:40:00 | 22:55:00 | |
| 3 | OHP | VF1A | OLr acted | reset | 22:30:00 | 22:40:00 | |
| 4 | OHP | TT3 on co 16 | LT not working,power mpcb tripped,pcrd cable tightened | mpcb made on,pcrd cable adjusted | 04:45:00 | 05:15:00 | |
| 5 | OHP | co 26 | olr acted | reset | 00:20:00 | 00:25:00 | |
| 6 | OHP | TBS on co 21 | pcrd fault,guide problem | informed mech,drum arrested | 03:30:00 | 03:45:00 | |
| 7 | OHP | CC 28 | OLr acted | reset | 23:50:00 | 00:00:00 | |
| 8 | CHP | CC 15 | olr acted | reset | 22:30:00 | 22:40:00 | |
| 9 | CHP | CC 35 STK2 | LT not working,M1 tripped | reset | 23:10:00 | 23:20:00 | |
| 10 | CHP | CC 104 scr9 | luff not working,110 v common high fuse blown | fuse replaced | 04:35:00 | 04:50:00 | |
| 11 | WT | OP 10 | PLC DI and DO card showing error | 12 slot rack back plane and DI ,DO card replaced than ok | 22:00:00 | 01:00:00 | PLC pinging intermittent ,to be checked ethernet cable from wireless modem to PLC(no delay) |