



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/09/2026

Shift: A

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Overload acted	Reset done	09:45:00 10:30:00	09:50:00 10:35:00	
2	OHP	BRC ON CO-8A	Oil temperature high trip. Air blast cooler MPCB tripped	Reset done	10:45:00	11:00:00	
3	OHP	VF-10	Tripping. Feedrate adjustment done	from 90 to 50	12:00:00	14:00:00	
4	OHP	CO-10A	Overload acted	Reset done	11:50:00	12:00:00	
5	OHP	VF-10	Reported tripped	MPCB tripped due to more load. Counter weight adjustment done and tested okay	12:10:00	14:00:00	
6	CHP	SCR-7 ON CC-40	Boom conveyor not running. Signal missing	LT done. Then OK	09:00:00	09:15:00	
7	CHP	SCR-3 ON CC-37	LT not working. Drive tripped	Reset done	10:00:00	10:10:00	
8	CHP	SCR-4 ON CC-111	Slew not working. Checked and found OK	.	11:05:00	11:20:00	
9	CHP	SCR-3 ON CC-37	Boom conveyor not running. Found OLR acted	Reset done	13:40:00	13:55:00	
10	CHP	CC-08	Belt sway acted	Loop wire loose at I/O rack. Tightened	08:30:00	08:40:00	
11	CHP	CC-21(C/D)	Reported tripped	OLR acted. Reset done	09:40:00	09:50:00	
12	WT	CP-2	Pusher moved to power cut off section	Jumpers placed pusher moved back and jumpers removed	07:00:00	07:20:00	NO delay