वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 02/11/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-64	MPCB tripped	reset done	01:40:00	01:50:00	
2	OHP	TBS ON CO-22	Left B/C stopping on ZSS> found cage struck up with material	Made free and tested OK	23:37:00	23:54:00	
3	OHP	TBS ON CO-7A	C/S not getting reset.	Cleaned the sensor and made reset. Then OK	23:37:00	23:54:00	
4	OHP	CO-25	OLR acted	Reset done	23:18:00	23:27:00	
5	OHP	WOBR ON CO-26	LT pushbutton not working. Found LT reverse pushbutton got stuck up.	Released and made OK	01:43:00	01:58:00	
6	OHP	WOBR ON CO-26	Luffing not working. OLR acted	Reset done	02:39:00	02:48:00	
7	OHP	TBS ON CO-20	LT not working. Found M-4 tripped	Reset done	05:44:00	05:53:00	
8	CHP	SCR-6 ON CC-38	LT not working. PCRD over tension acted	Released and made OK	01:30:00	01:40:00	
9	CHP	CC-32	Tripped on earth fault	Reset done	03:15:00	03:25:00	
10	CHP	CC-215	Overload acted	Reset done	03:20:00	03:30:00	
11	CHP	SCR-9 ON CC-104	Bucket wheel not running. Found slew MCCB tripped	Reset done	04:20:00	04:30:00	
12	CHP	SCR-9 ON CC-104	B/W not running. Found Cooler fan MPCB tripped	Reset done	05:30:00	05:40:00	
13	CHP	SCR-8 ON CC-213	Operator cabin lighting failed. cable cut.	cable jointing done and lighting made OK	03:25:00	04:00:00	

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 02/11/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	CC-107	Overload acted	Reset done	04:50:00	05:00:00	
15	CHP	CC-54 TO CC-58	Conveyors stopping frequently. Found processor-D0 not communicating. OFC not healthy. Changed ethernet cable from proc-c and made communicating.	comm.delay time monitoring between proc-c to proc-d increased	22:30:00	00:30:00	conveyors stopped 5 times. To be checked further
16	CHP	CC-22	C/S acted. checked and found module side loose contact	Tightness done and made OK	22:35:00	22:45:00	
17	WT	CO-3	Overload acted	Reset done	05:00:00	05:05:00	