



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 23/05/2026

Area: OHP

Equipment	Job
WOBR-1,2,3	Bucket wheel motors inspection is done.
WOBR-4 on co-6a	LT M5 5.5KW motor failed, removed and shifted to HVMCC-1, coupling removed and sent to ERS. Spare motor is made ready , needs to be fixed on WOBR-4. Yard ZSS interlock cage cotter pin missing, fixed properly.
TT-2	LT movement is done and checked cable winding and unwinding, Few guide rollers were damaged , spare rollers were asked to be made ready.
om-10 and LC-6	de watering is done.
cr-1 ; vf-21	motor and panel side ppm is done.
co-13a,14a,14b h/e hoists	hoists ppm is done.
co-64, 38b	field control cables dressing is done and switch board provided wherever camera is being installed.
co-28 pullchord / estop lamp	2.5*2c Al cable laid from CJB to yard entrance for lamp circuit.
brc-5 on co-32	yard interlock zss arrangement is modified and trail run taken.
brc-4 on co-8a	After mechanical job trail run of BRC is taken and found ok. CJB-2 and PJB on b/w-1 doors are fixed properly.
BRC-1 on co-28	LT preset Speed 2 (150rpm) is configured for REV CMD. A spare DI is configured in parallel with REV CMD, which selects Preset speed 2. HT transformer oil level is checked , found ok.