



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/09/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	Cc-52	MPD tripped	Reset done	17:00:00	17:05:00	
2	OHP	CO-48	Reported tripped	OLR acted.Reset done	18:50:00	19:00:00	
3	OHP	RCO-1A	ZSS acted	Probe gap adjusted and tested okay	19:10:00	19:20:00	
4	OHP	WOBR on CO-26	Reported B/C not running	Chute sensor acted.Not resetting	21:15:00	21:45:00	Informed to operation to inform to instrumentation
5	OHP	WOBR on CO-25	LT not taking place	PCRD MPCB tripped.Spare core got cut and got damaged at motor.Tapped and tested okay	21:48:00	22:05:00	
6	CHP	CC-109	BRS acted	Sensors cleaning done and tested okay	15:10:00	15:20:00	
7	CHP	CC-37	Reported not running	MPD tripped on phase fault.MCCB spark observed.One pole contact not making.MCCB replaced from CC-37 module,motor checked and found okay and tested	18:58:00	19:41:00	MCCB to be replaced for CC-34
8	CHP	SCR-10 on CC-105	Reported B/C not running	Checked and found communication problem.ZSS cage brought down,probe found damaged.Replaced and tested okay	20:30:00	21:50:00	Modem to be checked
9	CHP	SCR-3 on CC-37	LT not taking place	M-8 tripped due to bogey problem	20:10:00	20:20:00	Informed to mechanical
10	CHP	SCR-8 on CC-112	B/C not running	Checked and found material jamming.	20:20:00	20:40:00	Informed to operation
11	WT	OT-4	Reported not rotating in reverse	Checked and found drive panel E-stop acted.Released and tested okay	18:20:00	18:30:00	No delay as rake was not there