



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 13/05/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment        | Problem                                                                                    | Action                                                                          | From     | To       | Remarks                                                        |
|-------|------|------------------|--------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|----------|----------|----------------------------------------------------------------|
| 1     | OHP  | BRC on CO 34     | b/c not running,empg PB operated near operator cabin                                       | EMG PB released                                                                 | 00:45:00 | 01:00:00 |                                                                |
| 2     | CHP  | scr 10 on cc 105 | no power, 3 no's fuse blown in I/O,i/c 2 tripped in LC2,coupler @ drive end having problem | i/c made on, coupler and slip ring side opened,megger done one phase zero value | 23:00:00 | 00:20:00 | loop provide d,informed MVN murty sir,DNW will come in A shift |
| 3     | CHP  | CC 106 s2        | slew not working,jamming in slew area                                                      | informed operation                                                              | 02:35:00 | 02:45:00 |                                                                |
| 4     | CHP  | CC 33 SCR2       | b/c is stopping,communication problem                                                      | yard interlock zss kept in ckt and probe replaced                               | 02:40:00 | 03:15:00 |                                                                |
| 5     | CHP  | CC 104 scr 6     | slew not working,right side,coal jamming                                                   | informed operation                                                              | 02:40:00 | 02:55:00 |                                                                |
| 6     | CHP  | CC 38 SCR5       | b/c not running,olr acted                                                                  | reset                                                                           | 03:00:00 | 03:15:00 |                                                                |
| 7     | CHP  | LC 19            | fdr1 tripped                                                                               | made it on                                                                      | 04:50:00 | 05:10:00 |                                                                |
| 8     | CHP  | CC 51            | mpd acted                                                                                  | reset                                                                           | 02:50:00 | 02:55:00 |                                                                |
| 9     | CHP  | CC 58 TT         | signal not coming,fuse blown                                                               | fuse replaced                                                                   | 22:30:00 | 23:30:00 | kept in ckt                                                    |
| 10    | WT   | OP4              | slow moving,sensor problem                                                                 | sensor bypassed                                                                 | 00:30:00 | 00:50:00 |                                                                |