वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 29/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | TBS on co 19 | Left BC not working,OLr acted | reset | 14:50:00 | 15:15:00 | |
| 2 | OHP | BRC on CO 32 | LT not working ,D2 olr acted | OLR reset | 16:30:00 | 16:40:00 | |
| 3 | OHP | CR 3 | mpr tripped due to Oc | reset | 16:40:00 | 16:50:00 | |
| 4 | OHP | TBs on CO 21 | right luff not working | checked found no power supply to motor due to malfunctioning of OLR and bridge rectifier of brake ckt fully rusted and one side connector broken | 20:00:00 | 22:00:00 | told agency to bring spare for OLR and bridge rectifier and to be changed(pending) |
| 5 | OHP | CBMS on CO6A | mpcb tripped immediately after cmd | water inside motor,IR value zero | 18:50:00 | 22:00:00 | motor changing going on |
| 6 | CHP | LC 17 and 18 | no power,in LBDS FDR1 tripped in DMT | reset it and normalize LC17 and 18 both i/c 1 and 2 made on b/c made off | 14:45:00 | 15:15:00 | |
| 7 | IOSA | BRC | Lt not working,s/s in local | kept in remote | 14:20:00 | 14:30:00 | |